

- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles



43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding

**09 East Elevation**  
22% Window SF facing public Right of Way  
4% Wood Accent Trim

Building Number 1  
Building Type I



41% Thin Brick, 28% Cultured Stone, 31% Wood Siding  
5% Wood Accent Trim

**05 South Elevation**

Building Number 1  
Building Type I



43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding

**04 West Elevation**  
22% Window SF facing public Right of Way  
4% Wood Accent Trim

Building Number 1  
Building Type I





41% Face Brick, 44% Thin Brick, 15% Wood Siding  
28% Windows SF facing Public Right of Way  
5% Wood Accent Trim

**01 North Elevation**

Building Number 1  
Building Type I

# Post Oak Apartments





- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles



50% Face Brick, 25% Thin Brick, 11% Cultured Stone, 4% Wood Siding

Building Number 2  
Building Type III

**09 East Elevation**  
28% Window SF facing public Right of Way  
5% Wood Accent Trim



29% Face Brick, 31% Thin Brick, 9% Cultured Stone, 31% Wood Siding  
5% Wood Accent Trim

Building Number 2  
Building Type III

**05 South Elevation**



43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding

Building Number 2  
Building Type III


**04 West Elevation**  
22% Window SF facing public Right of Way  
4% Wood Accent Trim




52% Face Brick, 38% Thin Brick, 4% Cultured Stone, 6% Wood Siding

Building Number 2  
Building Type III

**01 North Elevation**  
26% Window SF facing public Right of Way  
5% Wood Accent Trim



# Post Oak Apartments



- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles



4% Wood Accent Trim

43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding

09 South Elevation Building Number 3 Building Type II



74% Painted Thin Brick, 26% Cultured Brick

32% Thin Brick, 19% Cultured Stone, 49% Wood Siding 5% Wood Accent Trim

Building Number 2 Building Type III

Building Number 3 Building Type II

05 West Elevation



52% Face Brick, 37% Thin Brick, 4% Cultured Stone, 7% Wood Siding


28% Windows SF facing Public Right of Way 5% Wood Accent Trim

Building Number 3 Building Type II

01 East Elevation

# Post Oak Apartments





- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles



43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding  
4% Wood Accent Trim


09 East Elevation Building Number 4 Building Type II



28% Thin Brick, 23% Cultured Stone, 49% Wood Siding 5% Wood Accent Trim

05 North Elevation

Building Number 4 Building Type II




56% Face Brick, 33% Thin Brick, 4% Cultured Stone, 7% Wood Siding 5% Wood Accent Trim


28% Windows SF facing Public Right of Way

Building Number 4 Building Type II


01 South Elevation

# Post Oak Apartments







- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles




9% Face Brick, 61% Thin Brick, 4% Cultured Stone, 26% Wood Siding  
 28% Windows SF facing Public Right of Way  
 Building Number 5  
 Building Type IV  
 4% Wood Accent Trim  
 Break Line  
 Break Line  
 (09) South Elevation



4% Wood Accent Trim  
 65% Cultured Stone, 35% Wood Siding  
 Break Line  
 Break Line  
 Building Number 5  
 Building Type IV  
 (05) East Elevation




39% Face Brick, 41% Thin Brick, 14% Cultured Stone, 16% Wood Siding  
 4% Wood Accent Trim  
 Break Line  
 Break Line  
 Building Number 5  
 Building Type IV  
 (07) North Elevation



32% Face Brick, 55% Thin Brick, 4% Cultured Stone, 9% Wood Siding  
 5% Wood Accent Trim  
 Building Number 5  
 Building Type IV  
 28% Windows SF facing Public Right of Way  
 Break Line  
 Break Line  
 (01) West Elevation



# Post Oak Apartments



- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color
  - Standing Seam Metal Roof
  - Composition Roof Shingles

22% Window SF facing public Right of Way  
4% Wood Accent Trim



43% Face Brick, 43% Thin Brick, 12% Cultured Stone, 2% Wood Siding

09 North Elevation Building Number 6 Building Type II




5% Wood Accent Trim

60% Thin Brick, 22% Cultured Stone, 18% Wood Siding

28% Windows SF facing Public Right of Way

Building Number 6 Building Type II

05 West Elevation




32% Face Brick, 55% Thin Brick, 4% Cultured Stone, 9% Wood Siding

5% Wood Accent Trim


Building Number 6 Building Type II

01 East Elevation


# Post Oak Apartments



# Post Oak Apartments



- Legend**
- Cultured Stone
  - Pre-Finished Metal Siding
  - Painted Thin Brick
  - Painted Wood Siding Burgundy Color
  - Standing Seam Metal Roof



9% Metal, 50% Cultured Stone, 40% Painted Thin Brick 1% Painted Wood Siding 4% Wood Accent Trim

Building Number 7


09 Leasing Office East Elevation




9% Metal, 66% Cultured Stonet, 20% Painted Thin Brick  
28% Windows SF facing Public Right of Way  
5% Wood Accent Trim

Building Number 7

01 Leasing Office North Elevation






- Legend**
- Cultured Stone
  - Pre-Finished Metal Siding
  - Painted Thin Brick
  - Painted Wood Siding Burgundy Color
  - Standing Seam Metal Roof
  - Back of Fire Place Brick



9% Metal, 40% Cultured Stone, 50% Painted Thin Brick      1% Painted Wood Siding      4% Wood Accent Trim

Building Number 7

09 Leasing Office West Elevation



40% Cultured Stone, 60% Painted Thin Brick      4% Wood Accent Trim

Building Number 7

01 Leasing Office South Elevation

# Post Oak Apartments




Post Oak Apartments



52% Cultured Stone, 40% Thin Brick, 8% Wood Siding **14** Rear Elevation - Boiler - Maint Building



60% Cultured Stone, 40% Thin Brick **11** Rear Elevation - Garage Building



- Legend**
- Painted Wood Siding Ochre Color
  - Painted Wood Siding Burgundy Color
  - Cultured Stone
  - Face Brick
  - Painted Face Brick
  - Painted Thin Brick
  - Painted Wood Siding White Color




55% Cultured Stone, 45% Thin Brick **07** Typ. End Elevation - Boiler - Maint Building



55% Cultured Stone, 45% Thin Brick **05** Typ. End Elevation - Garage Building



27% Cultured Stone, 29% Thin Brick, 34% Wood Siding **03** Front Elevation - Boiler - Maint Building



29% Cultured Stone, 27% Thin Brick, 34% Wood Siding **01** Front Elevation - Garage Building

