
Case No. 14-008ME


Legacy Apartments



Location Map



Aerial Exhibit







South Elevation - 80% Masonry (46% Brick, 34% Stone, 20% Stucco)









North Elevation - 65% Masonry (36% Brick, 29% Stone, 35% Stucco)



West Elevation - 71% Masonry (51% Brick, 20% Stone, 29% Stucco)



East Elevation - 61% Masonry (36% Brick, 25% Stone, 35% Stucco)



South Elevation - 69% Masonry (39% Brick, 30% Stone, 31% Stucco)









North Elevation - 61% Masonry (31% Brick, 30% Stone, 39% Stucco)



West Elevation - 61% Masonry (36% Brick, 25% Stone, 39% Stucco)




South Elevation - 87% Masonry (76% Brick, 11% Stone, 13% Stucco)



West Elevation - 86% Masonry (68% Brick, 18% Stone, 14% Stucco)









East Elevation - 79% Masonry (58% Brick, 19% Stone, 21% Stucco)



North Elevation - 82% Masonry (51% Brick, 31% Stone, 18% Stucco)








West Elevation - 86% Masonry (53% Brick, 33% Stone, 14% Stucco)









East Elevation - 78% Masonry (57% Brick, 21% Stone, 22% Stucco)



North Elevation - 86% Masonry (74% Brick, 12% Stone, 14% Stucco)



East Elevation - 70% Masonry (53% Brick, 17% Stone, 30% Stucco)



South Elevation - 79% Masonry (45% Brick, 34% Stone, 21% Stucco)









North Elevation - 76% Masonry (32% Brick, 44% Stone, 24% Stucco)



West Elevation - 63% Masonry (36% Brick, 27% Stone, 37% Stucco)



South Elevation - 63% Masonry (36% Brick, 27% Stone, 37% Stucco)

East Elevation - 80% Masonry (40% Brick, 40% Stone, 20% Stucco)













North Elevation - 63% Masonry (36% Brick, 27% Stone, 37% Stucco)



East Elevation - 70% Masonry (53% Brick, 17% Stone, 30% Stucco)



South Elevation - 74% Masonry (40% Brick, 34% Stone, 26% Stucco)









North Elevation - 69% Masonry (33% Brick, 36% Stone, 31% Stucco)



West Elevation - 63% Masonry (36% Brick, 21% Stone, 37% Stucco)



Proposed Covered Parking Structure

