

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Previous repairs to roofing materials



Previous repairs to roofing materials



Shingle damage




Shingle damage (possible source of water stain in southeast office ceiling)

Photos of roof and chimneys
prior to repair

Inspection Report



Post roof repair and shingle replacement and chimney repair



Before and after photos of SW corner of the building where brink and stucco were restored



Façade damage for repair



Façade damage on northside (porch)



Downspouts that were not tied into a underground drain for repair



Updated Façade, roof, and chimneys



Updated façade and chimneys



Updated façade and chimney.

