
Avilla McKinney Site Plan

15-316SP




Location Map



Aerial Exhibit





Site Plan








Landscape Plan











(01) Front Elevation - 1C





Material Elevation Percentages Masonsy = 90% Fiber Certent = 4%



03 Right Elevation - 2A






02) Rear Elevation - 2A





61 Front Elevation - 2A





Material Elevation Percentages Macony = 90% Fiber Cement = 4% (Fiber cement indudes all siding.




(03) Right Elevation - 2B






02) Rear Elevation - 2B

Material Sevation Percentages, Macony = 50% Fiber Cement = 42% (Fiber cement includes all siding time, and columns)



01) Front Elevation - 2B




Material Elevation Percentages Material 99% Fiber Cement = 4% (Fiber Cement Includes all skilling, time, and columns)




Front Elevation - 2C

Material Elevation Percentages Masony = 50% Fiber Cement =42%









04) Left Elevation - 3A

Material Elevation Percentages.
Masonsy = 62%.
Piber Cement = 30%.
(Fiber cement indudes all siding, trims, and columns).



Right Elevation - 3A





Rear Elevation - 3A


Material Devator Percentages Masonry = 54% Fiber Cement = 46% (Fiber cement includes all string, tring, and columns)



(01) Front Elevation - 3A











04) Left Elevation - 3B

(02) Rear Elevation - 3B

Material Elevation Percentages. Macony = 62% Fiber Cement = 38% (Fiber cement indudes all siding, trins, and columns)










Material Elevation Percentages Masonry = 62%



Left Elevation - 3C




03 Right Elevation - 3C (


Material Elevation Percentages Macony = 63%, Fiber Cement = 37%, (Fiber cement includes all skiling, time, and columns)




(02) Rear Elevation - 3C




01) Front Elevation - 3C





people and abligate Contain to Printed States (States States


finish gods of our stop hom Braker at a possible







Material Elevation Percentages Masony = 100% Fiber Cement = 0%

(Fiber cement indudes all sidin trims, and columns)















02 Rear Elevation



03 Right Elevation

(01) Front Elevation