

Substandard Structure Checklist

*Reference – City of McKinney Texas Code of Ordinances, Chapter 126, Article II, Division 3 Housing and Substandard Building Code

DATE: 2/7/18						
BUILDING INSPECTOR: Jackie Buckett						
PROPERTY ADDRESS: 408 E Standifer St						
Property Condition: Checked boxes indicate a deficiency						
High Grass	Trash	Debris	Fencing	Abandone	d Vehicles	
Dwelling	Commercial	Accessory	Story:	Number of Units:		
Frame	Masonry	Fire Damage	Vacant	Unsecured	Posted	
" <u>ALL STRUCTURES MUST MEET CURRENT BUILDING CODES</u> "						
EXTERIOR WALLS X Satisfactory Unsatisfactory Comments: The siding was installed prematurely, I was not able to see if the windows had been properly flashed. Requirement:						
Kequitement.						
Satisfactory X Unsatisfactor Comments: Not Requirement:	•	<u>FOUNDA</u>	<u>TION</u>			
1						

	Satisfactory
Х	Unsatisfactory

ROOF

Comments: Missing shingles on about half of the house and in two areas on the garage

Requirement:

PORCHES

X Satisfactory Unsatisfactory

Comments: The front porch appeared to be good.

Requirement:

WINDOWS AND DOORS

Satisfactory X Unsatisfactory

Comments: Exterior doors are ok, has a broken window on the east side.

Requirement:

INSIDE WALL / CEILINGS

X Satisfactory Unsatisfactory

Comments: The interior of the house appears to be ready for the second round of inspections. (frame, electric rough, plumbing and HVAC)

Requirement:

<u>STEPS</u>

X Unsatisfactory

Satisfactory

Comments: The steps at the front of the house are too small and the steps for the rear of the house are missing.

Requirement:

FLOORS

X Satisfactory Unsatisfactory

Comments: Floors are not finished at this point, but appear to be sound.

Requirement:

PLUMBING

Satisfactory X Unsatisfactory

Comments: The plumbing appears to be at the "Top/Out" stage for a house under construction. Rough stage, no fixtures except for the bath tubs.

Requirement:

ELECTRICAL

Satisfactory X Unsatisfactory

Comments: The electrical appears to be at the "Electric rough" stage for a house under construction.

Requirement:

MECHANICAL

Satisfactory X Unsatisfactory

Comments: The mechanical appears to be at the "Mechanical rough" stage for a house under construction.

Requirement:

ALL STRUCTURES MUST MEET THE FOLLOWING CODES:

2015 International Residential Code 2015 International Building Code 2015 International Energy Conservation Code 2015 International Mechanical Code 2015 International Plumbing Code 2017 National Electrical Code

Inspection Comments and Recommendations:

If the option to rehabilitate is extended, the structure must be brought up to 2015 International Residential codes for Structural, Electrical, Plumbing and Mechanical. All damaged framing shall be replaced. Any deviation from the original plan would require an engineered design. <u>All interior sheathing shall be removed for inspection.</u> Replace any damaged to the roof system including new shingles, decking, and rafters, and properly support. Replace all damaged windows and doors, jambs and sashes. Replace the electrical system with new conductors, devices and fixtures where required. Add AFCI and GFCI receptacles where required by 2015 IRC. Install hard wired smoke detectors with battery back-up. Replace the plumbing system to the city tap with new materials and install code approved plumbing fixtures. Install the water heater to code. Repair or install a code approved primary source of heat.

Other issues not specifically addressed herein may arise during the inspection process. In any case, these issues must meet code requirements notwithstanding.

Jackie Buckett City of McKinney Chief Building Inspector C-214-682-9887 O-972-547-2640 jbuckett@mckinneytexas.org www.mckinneytexas.org



Please tell us how we are doing - Building Inspection Department Survey

City of McKinney, P.O. Box 517, McKinney, TX 75070 Page 5