

4B23-11 Request to Amend (Drainage Remediation)



Wood rot near Chapel foundation



Wood rot at base of Chapel stairs



Lower level garden
(concrete bags as temporary barrier)



Upper level garden
where flooding initiates