
Herndon Street Abandonment / Thomason Tire Access Study

Regular Council Meeting September 19, 2017




CURRENT SITE PLAN FOR CHESTNUT COMMONS PARKING GARAGE










Looking Towards Herndon St from McDonald St








Herndon St Westbound from McDonald St/SH 5









Herndon St Westbound (Between SH 5 & Chestnut)








Chestnut St (Looking Towards Herndon St)




THOMASON TIRE – EXISTING OPERATIONS






THOMASON TIRE – EXISTING OPERATIONS





THOMASON TIRE – EXISTING OPERATIONS











Chestnut St (Looking Towards Hunt St)



























Chestnut St (Looking Towards Herndon St)











HERNDON STREET ABANDONMENT (CHESTNUT TO SH 5) EVALUATION SUMMARY

PROS	CONS
INCREASED CAPACITY & COST EFFICIENCY OF PROPOSED PARKING GARAGE STRUCTURE SERVING THE HISTORIC DOWNTOWN AREA.	SITE & ACCESS IMPACTS TO THOMASON TIRE AS IT RELATES TO THEIR CURRENTLY UNDERSTOOD SITE OPERATIONS WHICH MAY REQUIRE SIGNIFICANT ON-SITE IMPROVEMENTS TO MAINTAIN EXISTING OPERATIONS.
ELIMINATES SUBSTANDARD CITY STREET SECTION OF HERNDON WHICH IS CURRENTLY ONLY APPROXIMATELY 16 FEET WIDE.	ADDITIONAL MINOR COSTS WOULD BE REQUIRED TO ABANDON/RELOCATE WATER & WASTEWATER ALONG HERNDON STREET (±\$40,000).
SITE ACCESS TO THOMASON TIRE MAY ULTIMATELY BE AFFECTED BY THE PLANNED IMPROVEMENTS TO SH 5/MCDONALD STREET.	ADDITIONAL MINOR COSTS WOULD BE REQUIRED TO IMPROVE THE INTERSECTION OF CHESTNUT/HUNT TO IMPROVE ACCESS FOR LARGER TRUCKS (±\$20,000).
BASED ON TURNING SOFTWARE ANALYSIS, LARGER TRUCKS ACCESSING THOMASON TIRE ARE REQUIRED TO OVERTAKE MULTIPLE LANES TO TURN INTO THE SITE. ABANDONMENT OF HERNDON WOULD FORCE TRUCK TRAFFIC TO ACCESS THE SITE INITIALLY FROM HUNT STREET WHICH MAY PROVIDE A SAFER AND MORE PREDICTABLE TRUCK TRAFFIC ROUTE.	ADDITIONAL FRANCHISE UTILITY RELOCATION COSTS.
ELIMINATES POSSIBILITY OF TRUCK TRAFFIC HITTING PARKING GARAGE STRUCUTRE WHILE ATTENPTING TO ACCESS THOMASON TIRE VIA HERNDON STREET.	INCREASE IN TRUCK TRAFFIC ALONG HUNT STREET IN THE EVENT ON- SITE IMPROVEMENTS ARE NOT MADE.
HERNDON STREET WOULD ONLY ULTIMATELY SERVICE ONE BUSINESS (THOMASON TIRE) AND THAT BUSINESS CURRENTLY HAS ALTERNATE ACCESS POINTS ALONG CHESTNUT, HUNT, AND SH 5/MCDONALD ST.	

