
Millennium
Meritorious Exception
14-048ME



Location Map




Aerial Exhibit








Total = 59% Masonry including Sticky Stone, Sticky Brick and Real Brick



NORTH ELEVATION

Total = 0% Hardi Siding



Total = 20% Real Brick
Total = 23% Cultured Brick
Total - 16% Cultureed Stone

Building Number 7 EAST ELEVATION

