

Representative photos of various drainage  
issues throughout McKinney

Jeans Creek Aerial Sewer Crossing impacted by creek scour



Sewer Break in Comegys Creek. Creek had eroded, exposing the pipe



Finch Park exposed sanitary sewer



Park Circle submerged and exposed sewer, concrete encased



Aerial sewer crossings catching debris



Aerial crossing catching debris



Custer Road bridge at Wilson Creek – shows incising of creek





Virginia Parkway bridge over Wilson Creek



Jeans Creek



Herndon Branch

