


BOWED TOP FRAME PIECE

DETERIORATION OF GLAZING AND PAINT

09.29.2010 11:3



FRAMES AND WINDOWS O




FRAMES AND WINDOWS OUT OF SQUARE

BOWED BOTTOM FRAME PIECE



BOWED TOP FRAME PIECE



DETERIORATION OF GLAZING AND PAINT



BOWED TOP FRAME PIECE




CONDENSATION PROBLEM



09

DETERIORATION OF GLAZING AND PAINT

09 18 2010 08




DETERIORATION OF GLAZING AND PAINT



09 29 2010 11

THREE ALUMINUM TRAILER STYLE WINDOWS ON PORCH ENCLOSED TO BE THE LAUNDRY ROOM



CONDENSATION PROBLEM