


Photos of roof and chimneys prior to repair

Inspection Report

Post roof repair and shingle replacement and chimney repair



Before and after photos of SW corner of the building where brink and stucco were restored





Façade damage for repair



Façade damage on northside (porch)



Downspouts that were not tied into a underground drain for repair



Updated Façade, roof, and chimneys



Updated façade and chimneys



Updated façade and chimney.

