

A photograph of the Shepherd's Center for Women in Christ building. The building is a single-story structure with a gabled roof. The roof shows significant damage, with large sections of shingles missing, exposing the underlying wooden structure. The exterior walls are made of light-colored stone or brick. A sign on the left side of the building lists services: "SHEPHERD'S CENTER FOR WOMEN IN CHRIST", "COUNSELING SERVICES", "WORKSHOP SERVICES", and "PRIVACY COURT". The building is surrounded by a grassy area and a paved road. A red timestamp "06-06-2024 12:27 PM" is visible in the bottom right corner.

06-06-2024 12:27 PM



